



L50 control box / centraline di controllo




BOX108



BOX109

Vin range	11..30V
Vout @12V	12V
Vout @24V	24V
Pout max @12V steady light / luce continua:	2 x 10W
Pout max @12V flashing light / lampeggiante 50%	2 x 20W



dip-switch settings / settaggi		A	B	C	Functions / funzioni
1	A	OFF	ON	OFF	Steady light / luce fissa
2	B	ON	ON	OFF	Flashing / lampeggio 50%
3	C	ON	OFF	ON	Flashing / lampeggio 20..<10%
4	Synchronized flashing / lampeggio sincronizzato				
5	Alternate flashing / lampeggio alternato				
6	OFF = 60 flash/min.; ON = 45 flash/min.				
7	Flashing duty cycle / duty cycle lampeggio: OFF: D.C.=20%; ON: D.C.=<10%				
8	Twilight / crepuscolare				
9	Night dimming ON / riduzione notturna ON				
10	Night dimming > / riduzione notturna > (dpsw9+dpsw10) (D.C.=35%)				